

Inspection Report Summary

Department: Rod Machining

Machine: Okuma WC 136 (M136)

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 57 minutes

Auditor: Ruben Abrenica

Inspected Date: Aug 26, 2024

Inspection Report

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 57 minutes

Auditor: Ruben Abrenica

Inspected Date: Aug 26, 2024

Department: Rod Machining

Machine: Okuma WC 136 (M136)

Model Number: L1060

Manufacturer: Okuma

Serial Number: 1584

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Entanglement in rotating chuck or part. Crush or laceration on tailstock.	2	2	1	PR2 4	Interlocked (not-easily defeatable) door on front of machine	Pass		
2	Third Party Protection	Pinch or drawn in by swarf conveyor.	2	2	1	PR2 4	Swarf conveyor partially guarded.	Pass		
3	Power Transmission	Entanglement or crush	2	2	1	PR2 4	barrier guards	Pass		
4	Other Hazards	Crush by clamp	2	2	1	PR2 4	Clamp interlocked to door	Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 57 minutes
Auditor: Ruben Abrenica
Inspected Date: Aug 26, 2024

Department: Rod Machining
Machine: Okuma WC 136 (M136)
Model Number: L1060
Manufacturer: Okuma
Serial Number: 1584

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 57 minutes
 Auditor: Ruben Abrenica
 Inspected Date: Aug 26, 2024

Department: Rod Machining
 Machine: Okuma WC 136 (M136)
 Model Number: L1060
 Manufacturer: Okuma
 Serial Number: 1584

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?		Pass		
2	Are Emergency Exits clearly identified?		Pass		
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		N/A		
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		N/A		
5	Are the Eyewash Stations working and clean, and unobstructed?		N/A		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 57 minutes
 Auditor: Ruben Abrenica
 Inspected Date: Aug 26, 2024

Department: Rod Machining
 Machine: Okuma WC 136 (M136)
 Model Number: L1060
 Manufacturer: Okuma
 Serial Number: 1584

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Are all the sprinkler heads in your location unobstructed?		Pass		
7	Is Access to the Electrical Panels clear and unobstructed?		N/A		
8	Are carts in good condition?		Pass		
9	Is the lighting all functioning properly and adequate for the area?		Pass		
10	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 57 minutes
 Auditor: Ruben Abrenica
 Inspected Date: Aug 26, 2024

Department: Rod Machining
 Machine: Okuma WC 136 (M136)
 Model Number: L1060
 Manufacturer: Okuma
 Serial Number: 1584

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Is the temperature in the area comfortable to work in?		Pass		
12	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
13	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass		
14	Are the employees using their PPE?		Pass		
15	Are all controlled substances labelled in accordance with GHS standards?		Pass		

Initials	General Manager	Production Manager	Supervisor		Employee
-----------------	-----------------	--------------------	------------	---	----------