

Inspection Report Summary

Department: Rod Machining

Machine: Okuma WC 193 (M193)

Pass / Fail: 95% Passed / 5% Failed

Time to Conduct Audit: 44 minutes

Auditor: Gurdeep Matharu

Inspected Date: Sep 16, 2024

Inspection Report

Pass / Fail: 95% Passed / 5% Failed
 Time to Conduct Audit: 44 minutes
 Auditor: Gurdeep Matharu
 Inspected Date: Sep 16, 2024

Department: Rod Machining
 Machine: Okuma WC 193 (M193)
 Model Number: LB1511
 Manufacturer: Okuma
 Serial Number: 4270

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Entanglement in rotating chuck or part. Crush or laceration on tailstock.	2	2	1	PR2 4	Interlocked (not-easily defeatable) door on front of machine.	Pass		
2	Third Party Protection	Pinch or drawn in by swarf conveyor.	2	2	1	PR2 4	Swarf conveyor partially guarded	Pass		
3	Power Transmission	Entanglement or crush	2	2	1	PR2 4	barrier guards	Pass		
4	Other Hazards	Crush in clamp	2	2	1	PR2 4	Clamp interlocked to door	Pass		

Pass / Fail: 95% Passed / 5% Failed
Time to Conduct Audit: 44 minutes
Auditor: Gurdeep Matharu
Inspected Date: Sep 16, 2024

Department: Rod Machining
Machine: Okuma WC 193 (M193)
Model Number: LB1511
Manufacturer: Okuma
Serial Number: 4270

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?	Print & post SWP	Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 95% Passed / 5% Failed
 Time to Conduct Audit: 44 minutes
 Auditor: Gurdeep Matharu
 Inspected Date: Sep 16, 2024

Department: Rod Machining
 Machine: Okuma WC 193 (M193)
 Model Number: LB1511
 Manufacturer: Okuma
 Serial Number: 4270

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?		Pass		
2	Are Emergency Exits clearly identified?	Need post	Fail	86817	
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Pass		
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Pass		
5	Are the Eyewash Stations working and clean, and unobstructed?		Pass		

Pass / Fail: 95% Passed / 5% Failed
 Time to Conduct Audit: 44 minutes
 Auditor: Gurdeep Matharu
 Inspected Date: Sep 16, 2024

Department: Rod Machining
 Machine: Okuma WC 193 (M193)
 Model Number: LB1511
 Manufacturer: Okuma
 Serial Number: 4270

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Are all the sprinkler heads in your location unobstructed?		Pass		
7	Is Access to the Electrical Panels clear and unobstructed?		Pass		
8	Are carts in good condition?		N/A		
9	Is the lighting all functioning properly and adequate for the area?		Pass		
10	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		

Pass / Fail: 95% Passed / 5% Failed
 Time to Conduct Audit: 44 minutes
 Auditor: Gurdeep Matharu
 Inspected Date: Sep 16, 2024

Department: Rod Machining
 Machine: Okuma WC 193 (M193)
 Model Number: LB1511
 Manufacturer: Okuma
 Serial Number: 4270

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Is the temperature in the area comfortable to work in?		Pass		
12	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
13	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass		
14	Are the employees using their PPE?		Pass		
15	Are all controlled substances labelled in accordance with GHS standards?		Pass		

Initials	General Manager	Production Manager	Supervisor 	Employee 
----------	-----------------	--------------------	--	--