

Inspection Report Summary

Department:	Graphics Lab
Machine:	Bambu 3D Printer
Pass / Fail:	50 % Passed / 50 % Failed
Time to Audit:	1 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 13, 2026

Inspection Report

Facility: Acadia Junior High


Department: Graphics Lab

Machine: Bambu 3D Printer

Model Number:

Manufacturer:

Serial Number:



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Print part	Burn, entanglement , crush		Pass	1	2	2	PR2 4	Full enclosure	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?	2026 Inspection - Create safe work procedure for printers	Fail
2.	Are all Emergency Stops clearly marked and functioning properly?		N/A

Safety Rep Signature:

A handwritten signature in black ink, consisting of a vertical line followed by a stylized, looped character, enclosed within a rectangular box.