

Inspection Report Summary

Department:	Metal Shop
Machine:	CamTool CNC Router
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	1 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 26, 2026

Inspection Report

Facility: Shaftesbury High School

Department: Metal Shop

Machine: CamTool CNC Router

Model Number: 48/48

Manufacturer: CamTool

Serial Number:




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Operate machine	Laceration, entanglement in cutter. Struck by carriage.		Pass	2	2	2	PR18	Enclosed in room with interlocked door	
Third party access	Laceration, entanglement in cutter. Struck by carriage.		Pass	2	2	2	PR18	Enclosed in room with interlocked door	
Watch operation of machine	Unable to properly watch cutting process and identify hazardous conditions		Pass	1	2	2	PR24	Enlarge window in door	
Set up machine or empty dust collector	Trip on power cord		Pass	1	2	2	PR24	Electrical outlet behind machine to eliminate tripping on cord	
Operate machine	Exposure to dust and debris		Pass	2	2	2	PR18	Interlock dust collector to machine operation	
Set up parts	Struck by parts not secured to table		Pass	2	2	2	PR18	Secure Room	
Operate machine	Entangle, crush, struck due to failure of safety system		Pass	2	2	2	PR18	Category 3 safety circuit	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		
2.	Are all Emergency Stops clearly marked and functioning properly?		

Safety Rep Signature:

A rectangular box containing a handwritten signature in black ink. The signature consists of the letters 'IEI' written in a stylized, cursive-like font. The 'I' is a simple vertical line, the 'E' is formed by a large loop with a horizontal crossbar, and the final 'I' is another simple vertical line.