Inspection Report Summary

Department: CNC
Machine: CRANE-18-JIB

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 2 minutes
Auditor: Jason Benedictson
Inspected Date: Jul 22, 2024

Inspection Report

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 2 minutes
Auditor: Jason Benedictson
Inspected Date: Jul 22, 2024

Department: CNC
Machine: CRANE-18-JIB
Model Number:
Manufacturer: Motivation
Serial Number:

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Apply rigging to the load	Hot mold, Heavy rigging, sharp edges	1	1	1	PR4 1	Training	**Pass**		
2	Lift load	Load falling, hitting and crushing, and/or equipment failure.	3	1	2	PR1 6	Overhead crane training and practical evaluation. Pre-use Inspection of crane and rigging.	**Pass**		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 2 minutes
Auditor: Jason Benedictson
Inspected Date: Jul 22, 2024

Department: CNC
Machine: CRANE-18-JIB
Model Number:
Manufacturer: Motivation
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 2 minutes
Auditor: Jason Benedictson
Inspected Date: Jul 22, 2024

Department: CNC
Machine: CRANE-18-JIB
Model Number:
Manufacturer: Motivation
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	The floors are clear of debris, loose material and trip hazards.		Pass		
2	The floors are not slippery or wet and there are no spills.		Pass		
3	Floors around furnaces and equipment are in good condition.		Pass		
4	Aisle are clear, no obstructions.		Pass		
5	Exits are clear and functioning.		Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 2 minutes
Auditor: Jason Benedictson
Inspected Date: Jul 22, 2024

Department: CNC
Machine: CRANE-18-JIB
Model Number:
Manufacturer: Motivation
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Fire extinguishers are clear of obstruction and are inspected regularly.		Pass		
7	Fire blanket(s) are in their holders and instructions are legible.		N\A		
8	Electrical panels have one meter clearance and are free of clutter.		Pass		
9	Chemical substances are properly labelled.		Pass		
10	Required Personal Protective Equipment (PPE) is available and being worn.		Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 2 minutes
Auditor: Jason Benedictson
Inspected Date: Jul 22, 2024

Department: CNC
Machine: CRANE-18-JIB
Model Number:
Manufacturer: Motivation
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Crane(s) and/or forklift(s) in good working order. Daily inspection log up to date.		Pass		
12	All equipment in good working order with proper guarding.		Pass		
13	Compressed gas cylinders clean, stored safely and secure.		N\A		
14	Extension cords and torch hoses do not pose a tripping hazard.		Pass		
15	There are no leaks; (oil, gas, water or compressed air).		Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 2 minutes
Auditor: Jason Benedictson
Inspected Date: Jul 22, 2024

Department: CNC
Machine: CRANE-18-JIB
Model Number:
Manufacturer: Motivation
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
16	Storage shelves and are in good condition and are loaded only to capacity.		Pass		
17	HVAC and exhaust system in working order and being used.		Pass		

Initials	General Manager	Production Manager	Supervisor	Employee