Inspection Report Summary

Department: QA
Machine: Brinell Hardness Tester

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 6 minutes
Auditor: Gaganjit Singh
Inspected Date: Nov 08, 2024

Inspection Report

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 6 minutes
Auditor: Gaganjit Singh
Inspected Date: Nov 08, 2024

Department: QA
Machine: Brinell Hardness Tester
Model Number: VD1
Manufacturer: Air-O-Brine
Serial Number: 106674

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Pinch. Struck by flying part.	2	1	1	PR3 2	Two-hand trigger (not hold-to-run). Hold-to-run foot pedal. Front shield.	**Pass**		
2	Third Party Protection	Struck by flying part	2	1	1	PR3 2	Located against a fence. Partial front shield.	**Pass**		
3	Power Transmission	Crush	2	1	1	PR3 2	Fixed barriers	**Pass**		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 6 minutes
Auditor: Gaganjit Singh
Inspected Date: Nov 08, 2024

Department: QA
Machine: Brinell Hardness Tester
Model Number: VD1
Manufacturer: Air-O-Brine
Serial Number: 106674

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 6 minutes
Auditor: Gaganjit Singh
Inspected Date: Nov 08, 2024

Department: QA
Machine: Brinell Hardness Tester
Model Number: VD1
Manufacturer: Air-O-Brine
Serial Number: 106674

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?		Pass		
2	Are Emergency Exits clearly identified?		Pass		
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Pass		
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Pass		
5	Are the Eyewash Stations working and clean, and unobstructed?		Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 6 minutes
Auditor: Gaganjit Singh
Inspected Date: Nov 08, 2024

Department: QA
Machine: Brinell Hardness Tester
Model Number: VD1
Manufacturer: Air-O-Brine
Serial Number: 106674

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Are all the sprinkler heads in your location unobstructed?		Pass		
7	Is Access to the Electrical Panels clear and unobstructed?		Pass		
8	Are carts in good condition?		Pass		
9	Is the lighting all functioning properly and adequate for the area?		Pass		
10	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 6 minutes
Auditor: Gaganjit Singh
Inspected Date: Nov 08, 2024

Department: QA
Machine: Brinell Hardness Tester
Model Number: VD1
Manufacturer: Air-O-Brine
Serial Number: 106674

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Is the temperature in the area comfortable to work in?		Pass		
12	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
13	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass		
14	Are the employees using their PPE?		Pass		
15	Are all controlled substances labelled in accordance with GHS standards?		Pass		

Initials	General Manager	Production Manager	Supervisor	Employee