

Inspection Report Summary

Department: Wood Shop

Machine: Laguna Jointer

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 5 minutes

Auditor: Jacob Tsai

Inspected Date: May 15, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 5 minutes

Auditor: Jacob Tsai

Inspected Date: May 15, 2025

Department: Wood Shop

Machine: Laguna Jointer

Model Number: MJ8X72P-0130 (230V, 1 PH, 12 A)

Manufacturer: Laguna

Serial Number: 2134496

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Operate machine	Laceration, amputation from blade	3	2	2	PR1 12	Spring-loaded guard			
2	Operate machine	Crush in power transmission	2	2	2	PR1 8	Fixed enclosure guard			

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 5 minutes
Auditor: Jacob Tsai
Inspected Date: May 15, 2025

Department: Wood Shop
Machine: Laguna Jointer
Model Number: MJ8X72P-0130 (230V, 1 PH, 12 A)
Manufacturer: Laguna
Serial Number: 2134496

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Initials	General Manager	Production Manager	Supervisor	Employee	
----------	-----------------	--------------------	------------	----------	---