

Inspection Report Summary

Department: STEM Lab

Machine: Modela CNC Router Patrick

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Jacob Tsai

Inspected Date: May 15, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Jacob Tsai
Inspected Date: May 15, 2025

Department: STEM Lab
Machine: Modela CNC Router Patrick
Model Number: MDX-50
Manufacturer: Modela
Serial Number:

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Operate machine	Laceration, crush, entangle	2	2	2	PR18	Interlocked enclosure guard			

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 0 minutes
 Auditor: Jacob Tsai
 Inspected Date: May 15, 2025

Department: STEM Lab
 Machine: Modela CNC Router Patrick
 Model Number: MDX-50
 Manufacturer: Modela
 Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		