

Inspection Report Summary

Department:	Corrugator
Machine:	10 Corrugator - Wet End - Deck (Bridge)
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	4 minutes
Auditor:	Iqbal Chowdhury
Inspected Date:	Dec 4, 2025

Inspection Report

Facility: Cascades Winnipeg


Department: Corrugator

Machine: 10 Corrugator - Wet End - Deck (Bridge)

Model Number:

Manufacturer:

Serial Number:



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Accessing the bridge (deck)	Possible fall from heights		Pass	3	2	1	PR2 6	Safety ladders in place at both points of access with safety gates installed at top of ladders entering/exiting the bridge (deck)	
Working on the bridge (deck) area	Possible fall from heights		Pass	3	2	1	PR2 6	Guardrail system installed around perimeter of area and safety gates at ladderway entrance/exit points	
Working on the bridge (deck) area and closer access to the web belting that carries the corrugate web towards dry-end	Possible slip/trip/fall if stepping onto moving belting		Pass	2	1	1	PR4 2	Only accessed during thread up and paper removal (low exposure). Belt movement is extremely slow (varies from .5 to .7 feet per second). If it is necessary to do continuous work then the deck belts would be locked out with the MHI.	
Working on the bridge (deck) area, moving around area	Overhead and low bump (head) hazards, hood and beam protrusions.		Pass	2	1	1	PR4 2	Generally only accessed during thread up and paper removal personnel are aware of low protruding areas. Sufficient lighting, and signage, and ability to avoid.	

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Working on the bridge (deck) area and exposure to moving paper web	Slip/trip/fall		Pass	1	1	1	PR4 1	even tough the paper seems to be moving at a high speed (80 to 150 meters per minute) if stepped on the paper web would break if pulled by the machinery system. There is also very infrequent access to this area	
Working on the bridge (deck) area, moving around area exposure to bridge (deck) planks coming loose, unsupported, or breakage	Slip/trip/fall		Pass	2	1	1	PR4 2	Periodic auditing through Wesguard system to ascertain board conditions. Hazard reporting system initiated by employees available when noticed during all operational times.	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Department Specific

#	Question	Corrective Action	Pass/Fail
1.	Are Emergency Exits clear and unobstructed?		Pass
2.	Are Emergency Exits clearly identified?		Pass
3.	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Pass
4.	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Pass
5.	Are the Eyewash Stations working and clean, and unobstructed?		Pass
6.	Are all the sprinkler heads in your location unobstructed?		Pass
7.	Is Access to the Electrical Panels clear and unobstructed?		Pass
8.	Are carts in good condition?		Pass
9.	Is the lighting all functioning properly and adequate for the area?		Pass
10.	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass
11.	Is the temperature in the area comfortable to work in?		Pass
12.	Are all air quality systems working (dust, fumes or vapour present)?		Pass
13.	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass
14.	Are the employees using their PPE?		Pass
15.	Are all controlled substances labelled in accordance with GHS standards?		Pass

Signatures (capture on paper after printing): _____