

Inspection Report Summary

Department:	Arts
Machine:	Clay Slab Roller
Pass / Fail:	75 % Passed / 25 % Failed
Time to Audit:	2 minutes
Auditor:	Kristin Petaski
Inspected Date:	May 13, 2026

Inspection Report

Facility: Arthur A. Leach Junior High

Department: Arts

Machine: Clay Slab Roller

Model Number:

Manufacturer:

Serial Number:



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Roll clay	Pinch, crush	2026 Inspection- sand edge of hinged guard to eliminate sharp edges 	Fail	1	2	2	PR2 4	Hazard decals, awareness barrier	
Roll clay	Pinch in gears		Pass	1	2	2	PR2 4	Fixed guard	
Third party access	Crush		Pass	1	2	2	PR2 4	Hazard markings on floor	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		N/A

Safety Rep Signature:

A handwritten signature in black ink, consisting of a large, stylized capital letter 'P' with a vertical line through it, enclosed within a rectangular box.