

Inspection Report Summary

Department:	Woodworking
Machine:	General International Thickness Planer
Pass / Fail:	83 % Passed / 17 % Failed
Time to Audit:	2 minutes
Auditor:	Kristin Petaski
Inspected Date:	May 13, 2026

Inspection Report

Facility: Arthur A. Leach Junior High

Department: Woodworking

Machine: General International Thickness Planer

Model Number: 30-125 (230V, 15A, 60HZ, 1PH, 3 HP)

Manufacturer: General International

Serial Number: PTSD15-000177



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Third party access	Laceration, amputation from blade		Pass	2	2	2	PR1 8	Guards and hazards markings on floor	
Operate machine	Laceration, amputation from tooling		Pass	2	2	2	PR1 8	Fixed infeed guard & hinged outfeed guard	
Feed short pieces	Contact with blade, kickback, struck by debris		Pass	2	2	2	PR1 8	Fixed guard to restrict short pieces. Label on machine indicated shortest piece is 12".	
Operate machine	Entangle, crush in power transmission		Pass	2	2	2	PR1 8	Replace guards	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?	2026 Inspection - knee-jerk jams. Replace with new controls and mushroom-style estop. 	Fail

Safety Rep Signature:

A handwritten signature in black ink, consisting of a large, stylized 'P' with a vertical line through it, enclosed within a rectangular box.