

Inspection Report Summary

Department:	Woodworking
Machine:	Router Table
Pass / Fail:	80 % Passed / 20 % Failed
Time to Audit:	4 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 13, 2026

Inspection Report

Facility: Vincent Massey Collegiate


Department: Woodworking

Machine: Router Table


Model Number:

Manufacturer:

Serial Number: PTSD15-000214



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Operate machine	Laceration, amputation from tooling	2026 Inspection - Replace broken shield 	Fail	2	2	2	PR1 8	Awareness shield over tooling	
Operate machine	Crush, entangle in power transmission		Pass	2	2	2	PR1 8	Fixed guard	
Third party walk through door	Walk into router, bump operator		Pass	2	2	2	PR1 8	Relocate router away from door	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

12