

# Inspection Report Summary

|                 |                           |
|-----------------|---------------------------|
| Department:     | Woodworking               |
| Machine:        | Rikon Woodworking Bandsaw |
| Pass / Fail:    | 75 % Passed / 25 % Failed |
| Time to Audit:  | 3 minutes                 |
| Auditor:        | Idongesit Inwang          |
| Inspected Date: | May 13, 2026              |

# Inspection Report

**Facility:** Vincent Massey Collegiate

**Department:** Woodworking

**Machine:** Rikon Woodworking Bandsaw

**Model Number:**


**Manufacturer:** Rikon

**Serial Number:**



## Machine Specific

| Activity/Tasks  | Hazards                                          | Corrective Action | Pass/Fail | Severity | Exposure | Avoidance | Total    | Current Safeguards                | Recommended Improvements |
|-----------------|--------------------------------------------------|-------------------|-----------|----------|----------|-----------|----------|-----------------------------------|--------------------------|
| Cut Part        | Laceration from blade                            |                   | Pass      | 2        | 2        | 2         | PR1<br>8 | Chip shield                       |                          |
| Operate Machine | Entanglement,<br>Contact with power transmission |                   | Pass      | 2        | 2        | 2         | PR1<br>8 | Secured power transmission guards |                          |

| #  | Question                                                         | Corrective Action                                                                                                                             | Pass/Fail |
|----|------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| 1. | Safe Work Procedure posted?                                      |                                                                                                                                               | Pass      |
| 2. | Are all Emergency Stops clearly marked and functioning properly? | 2026 Inspection - Remove one set of start/stop buttons<br> | Fail      |

**Safety Rep Signature:**

A rectangular box containing a handwritten signature. The signature consists of three stylized, vertical strokes that resemble the letters 'I', 'E', and 'I' written together. The lines are dark and slightly irregular, typical of a handwritten mark.