

Inspection Report Summary

Department:	Graphic Arts
Machine:	Thunder Laser engraver
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	1 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 20, 2026

Inspection Report

Facility: Oak Park High School

Department: Graphic Arts

Machine: Thunder Laser engraver

Model Number:

Manufacturer: Thunder Laser

Serial Number:




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Engrave Part	Entangle, Crush, Burn from Laser		Pass	2	2	2	PR18	Safety rated interlocked enclosure guard	
Operate Machine	Crush, entangle in power transmission devices		Pass	2	2	2	PR18	Enclosure guard	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A rectangular box containing a handwritten signature. The signature is written in black ink and appears to be a stylized representation of the letters 'J' and 'E'.