

Inspection Report Summary

Department:	Woodworking
Machine:	Rikon Lathe
Pass / Fail:	67 % Passed / 33 % Failed
Time to Audit:	7 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 21, 2026

Inspection Report

Facility: Ecole Charleswood Junior High


Department: Woodworking

Machine: Rikon Lathe

Model Number: 70-150VSR

Manufacturer: Rikon

Serial Number: 200804WF006




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Turn part	Entangle, debris		Pass	3	2	2	PR1 12	Awareness shield	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?	Remove one set of e-stops, preferably remove the knee jerk one 	Fail

Safety Rep Signature:

A rectangular box containing a handwritten signature. The signature consists of the letters 'IE' in a stylized, cursive-like font, followed by a long horizontal line extending to the right.