

Inspection Report Summary

Department:	Wood Shop
Machine:	Excelsior Router Table
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	0 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 27, 2026

Inspection Report

Facility: Bison Run School

Department: Wood Shop

Machine: Excelsior Router Table

Model Number: XL-075

Manufacturer: Excelsior

Serial Number:




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Operate machine	Laceration, amputation from blade		Pass	2	2	2	PR1 8	Awareness shield	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A rectangular box containing a handwritten signature. The signature consists of the letters 'L', 'E', and 'I' written in a cursive, stylized manner. The 'L' is on the left, the 'E' is in the middle, and the 'I' is on the right. The lines are dark and slightly irregular, suggesting a pen or marker.