

Inspection Report Summary

Department:	STEM Lab
Machine:	Ultimaker 2+ 3D Printer
Pass / Fail:	50 % Passed / 50 % Failed
Time to Audit:	0 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 27, 2026

Inspection Report

Facility: Bison Run School


Department: STEM Lab

Machine: Ultimaker 2+ 3D Printer

Model Number: 2+

Manufacturer: Ultimaker

Serial Number:




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Print part	Crush, burn		Pass	1	2	1	PR3 2	Fixed enclosure guard	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Fail
2.	Are all Emergency Stops clearly marked and functioning properly?		N/A

Safety Rep Signature:

A rectangular box containing a handwritten signature in black ink. The signature consists of the letters 'J', 'E', and 'I' written in a cursive, stylized manner. The 'J' is on the left, followed by the 'E', and the 'I' is on the right. The box is empty except for the signature.