

Inspection Report Summary

Department:	Power Mechanics
Machine:	Canbuilt Manual Press
Pass / Fail:	33 % Passed / 67 % Failed
Time to Audit:	2 minutes
Auditor:	Idongesit Inwang
Inspected Date:	Jun 16, 2026

Inspection Report

Facility: Sisler High School

Department: Power Mechanics

Machine: Canbuilt Manual Press

Model Number: 20 Tons

Manufacturer: Canbuilt

Serial Number: 32989




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Press part	Crush, struck by part	2026 Inspection - Install curtain across front 	Fail	1	2	2	PR2 4	Curtain across front	
Third party access	Crush, struck by part		Pass	1	2	2	PR2 4	Located against wall	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?	2026 Inspection - Create safe work procedure	Fail
2.	Are all Emergency Stops clearly marked and functioning properly?		N/A

Safety Rep Signature:

A rectangular box containing a handwritten signature. The signature consists of the letters 'J' and 'E' written in a cursive, stylized manner. The 'J' is on the left and the 'E' is on the right, with a horizontal line connecting them.