

Inspection Report Summary

Department:	Metalworking
Machine:	Summit Lathe
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	0 minutes
Auditor:	Idongesit Inwang
Inspected Date:	Jun 17, 2026

Inspection Report

Facility: Daniel McIntyre Collegiate

Department: Metalworking

Machine: Summit Lathe

Model Number:

Manufacturer: Summit

Serial Number: 710-103-shop equip-002



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Operate machine	Entangle in chuck		Pass	3	2	2	PR1 12	Interlock chuck guard	
Operate machine	Entangle, crush in power transmission		Pass	2	2	2	PR1 8	Fixed guards	
Third party access	Entangle from rear		Pass	3	2	2	PR1 12	Rear barrier	
Operate machine	Struck by debris, laceration from tooling		Pass	2	2	2	PR1 8	Fixed tool post shield	
Operate machine	Entangle in overstock feed		Pass	2	2	2	PR1 8	Cover overstock feed	
Operate machine	Entangle in lead screw		Pass	2	2	2	PR1 8	Lead screw cover	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A handwritten signature in black ink, consisting of a vertical line followed by a stylized, looped character, enclosed within a rectangular box.