

Inspection Report

Auditor: Damir Malenica
Inspected Date: May 29, 2023

Department: Assembly
Machine: Station 2 WC 620 (Tie Rod Assembly)
Model Number:
Manufacturer:
Serial Number:

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Press Parts	Crush-contact with press	2	2	2	PR18	Two Hand Controls			

Machine Specific

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?				
2	Are all Emergency Stops clearly marked and functioning properly?				

Department Specific

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?				
2	Are Emergency Exits clearly identified?				
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?				
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?				
5	Are the Eyewash Stations working and clean, and unobstructed?				
6	Are all the sprinkler heads in your location unobstructed?				

7	Is Access to the Electrical Panels clear and unobstructed?				
8	Are carts in good condition?				
9	Is the lighting all functioning properly and adequate for the area?				
10	Are noise levels adequate with PPE, any high impulse or continual noise?				
11	Is the temperature in the area comfortable to work in?				
12	Are all air quality systems working (dust, fumes or vapour present)?				
13	Is the housekeeping (floor and work surfaces) sufficient for the area?				
14	Are the employees using their PPE?				

15	Are all controlled substances labelled in accordance with GHS standards?				
----	--	--	--	--	--

Initials	General Manager	Production Manager	Supervisor <i>Daniel</i>	Employee <i>[Signature]</i>
-----------------	-----------------	--------------------	--------------------------	-----------------------------