

Inspection Report

Auditor: Karanvir Singh
Inspected Date: Jun 28, 2023

Department: Pattern Shop
Machine: Arboga Drill Press #3050
Model Number: G1630
Manufacturer: Arboga
Serial Number: 3050

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Entangle in spindle, laceration from tooling	2	2	1	PR2 4	Guard around spindle			
2	Third Party Protection	entangle, laceration	2	2	1	PR2 4	located against wall			
3	Power Transmission	Crush, entanglement	2	2	1	PR2 4	fixed guard			

Machine Specific

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?				
2	Are all Emergency Stops clearly marked and functioning properly?				

Department Specific

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?				
2	Are Emergency Exits clearly identified?				
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?				
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?				
5	Are the Eyewash Stations working and clean, and unobstructed?				
6	Are all the sprinkler heads in your location unobstructed?				

7	Is Access to the Electrical Panels clear and unobstructed?				
8	Are carts in good condition?				
9	Is the lighting all functioning properly and adequate for the area?				
10	Are noise levels adequate with PPE, any high impulse or continual noise?				
11	Is the temperature in the area comfortable to work in?				
12	Are all air quality systems working (dust, fumes or vapour present)?				
13	Is the housekeeping (floor and work surfaces) sufficient for the area?				
14	Are the employees using their PPE?				

15	Are all controlled substances labelled in accordance with GHS standards?				
----	--	--	--	--	--

<i>Initials</i>	General Manager	Production Manager	Supervisor <i>Kash</i>	Employee
-----------------	-----------------	--------------------	------------------------	----------