

Inspection Report

Pass / Fail: 94% Passed / 6% Failed

Time to Conduct Audit: 25 minutes

Auditor: Gurdeep Matharu

Inspected Date: Oct 25, 2023

Department: Rod Machining

Machine: Hydmech WC 83 (M84)

Model Number: H-18A

Manufacturer: Hydmech

Serial Number: N/A

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Crush or cut hazard at blade.	1	2	1	PR3 2	Fully guarded with interlocked doors.	Pass		
2	Third Party Protection	Crush or cut hazard at blade	1	2	1	PR3 2	Fully guarded with interlocked doors. Light curtain at offloading.	Pass		
3	Power Transmission	Entanglement or crush	1	2	1	PR3 2	fixed guarding	Pass		
4	Other Hazards	Crush at infeed and outfeed. Crush or entanglement at loading.	1	2	1	PR3 2	Light curtain at offloading.	Pass		

Pass / Fail: 94% Passed / 6% Failed
Time to Conduct Audit: 25 minutes
Auditor: Gurdeep Matharu
Inspected Date: Oct 25, 2023

Department: Rod Machining
Machine: Hydmech WC 83 (M84)
Model Number: H-18A
Manufacturer: Hydmech
Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?	Posted	Fail		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 94% Passed / 6% Failed
 Time to Conduct Audit: 25 minutes
 Auditor: Gurdeep Matharu
 Inspected Date: Oct 25, 2023

Department: Rod Machining
 Machine: Hydmech WC 83 (M84)
 Model Number: H-18A
 Manufacturer: Hydmech
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?		Pass		
2	Are Emergency Exits clearly identified?		N/A		
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Pass		
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Pass		
5	Are the Eyewash Stations working and clean, and unobstructed?		N/A		

Pass / Fail: 94% Passed / 6% Failed
 Time to Conduct Audit: 25 minutes
 Auditor: Gurdeep Matharu
 Inspected Date: Oct 25, 2023

Department: Rod Machining
 Machine: Hydmech WC 83 (M84)
 Model Number: H-18A
 Manufacturer: Hydmech
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Are all the sprinkler heads in your location unobstructed?		Pass		
7	Is Access to the Electrical Panels clear and unobstructed?		Pass		
8	Are carts in good condition?		Pass		
9	Is the lighting all functioning properly and adequate for the area?		Pass		
10	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		

Pass / Fail: 94% Passed / 6% Failed
 Time to Conduct Audit: 25 minutes
 Auditor: Gurdeep Matharu
 Inspected Date: Oct 25, 2023

Department: Rod Machining
 Machine: Hydmech WC 83 (M84)
 Model Number: H-18A
 Manufacturer: Hydmech
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Is the temperature in the area comfortable to work in?		Pass		
12	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
13	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass		
14	Are the employees using their PPE?		Pass		
15	Are all controlled substances labelled in accordance with GHS standards?		N/A		

Initials	General Manager	Production Manager	Supervisor 	Employee 
----------	-----------------	--------------------	--	--