

Inspection Report

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 244 minutes

Auditor: Pete Rempel

Inspected Date: Oct 27, 2023

Department: Green Sand Molding

Machine: Sand Transfer Belt #4105

Model Number: N/A

Manufacturer: N/A

Serial Number: 4105

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Entanglement in rollers	2	1	2	PR2 4	None	Pass		
2	Third Party Protection	Entanglement in rollers. Drawn into nip points.	2	1	2	PR2 4	Located on a mezzanine.	Pass		
3	Power Transmission	Crush, entanglement in motor, drive and tail drums, pulleys, etc.	2	1	2	PR2 4	Fixed guard around motor belt and drive drum.	Pass		
4	Other Hazards	N/A	2	1	2	PR2 4	N/A	Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 244 minutes
Auditor: Pete Rempel
Inspected Date: Oct 27, 2023

Department: Green Sand Molding
Machine: Sand Transfer Belt #4105
Model Number: N/A
Manufacturer: N/A
Serial Number: 4105

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 244 minutes
 Auditor: Pete Rempel
 Inspected Date: Oct 27, 2023

Department: Green Sand Molding
 Machine: Sand Transfer Belt #4105
 Model Number: N/A
 Manufacturer: N/A
 Serial Number: 4105

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?		Pass		
2	Are Emergency Exits clearly identified?		Pass		
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Pass		
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Pass		
5	Are the Eyewash Stations working and clean, and unobstructed?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 244 minutes
 Auditor: Pete Rempel
 Inspected Date: Oct 27, 2023

Department: Green Sand Molding
 Machine: Sand Transfer Belt #4105
 Model Number: N/A
 Manufacturer: N/A
 Serial Number: 4105

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Are all the sprinkler heads in your location unobstructed?		N/A		
7	Is Access to the Electrical Panels clear and unobstructed?		Pass		
8	Are carts in good condition?		N/A		
9	Is the lighting all functioning properly and adequate for the area?		Pass		
10	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 244 minutes
 Auditor: Pete Rempel
 Inspected Date: Oct 27, 2023

Department: Green Sand Molding
 Machine: Sand Transfer Belt #4105
 Model Number: N/A
 Manufacturer: N/A
 Serial Number: 4105

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Is the temperature in the area comfortable to work in?		Pass		
12	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
13	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass		
14	Are the employees using their PPE?		N/A		
15	Are all controlled substances labelled in accordance with GHS standards?		Pass		