

Inspection Report

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 2 minutes
Auditor: Randy Rickard
Inspected Date: Mar 11, 2024

Department: Casting
Machine: TBL-23-TIE-H8
Model Number:
Manufacturer:
Serial Number: TBL-23-TIE-H8

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Pouring Metal	Burn-contact with material	2	2	2	PR18	PPE	Pass		
2	Pouring Metal	Crush-contact with actuating cylinders	2	2	2	PR18	None	Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 2 minutes
Auditor: Randy Rickard
Inspected Date: Mar 11, 2024

Department: Casting
Machine: TBL-23-TIE-H8
Model Number:
Manufacturer:
Serial Number: TBL-23-TIE-H8

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 2 minutes
 Auditor: Randy Rickard
 Inspected Date: Mar 11, 2024

Department: Casting
 Machine: TBL-23-TIE-H8
 Model Number:
 Manufacturer:
 Serial Number: TBL-23-TIE-H8

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	The floors are clear of debris, loose material and trip hazards.		N/A		
2	The floors are not slippery or wet and there are no spills.		N/A		
3	Floors around furnaces and equipment are in good condition.		N/A		
4	Aisle are clear, no obstructions.		N/A		
5	Exits are clear and functioning.		N/A		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 2 minutes
 Auditor: Randy Rickard
 Inspected Date: Mar 11, 2024

Department: Casting
 Machine: TBL-23-TIE-H8
 Model Number:
 Manufacturer:
 Serial Number: TBL-23-TIE-H8

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Fire extinguishers are clear of obstruction and are inspected regularly.		N/A		
7	Fire blanket(s) are in their holders and instructions are legible.		N/A		
8	Electrical panels have one meter clearance and are free of clutter.		N/A		
9	Chemical substances are properly labelled.		N/A		
10	Required Personal Protective Equipment (PPE) is available and being worn.		N/A		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 2 minutes
 Auditor: Randy Rickard
 Inspected Date: Mar 11, 2024

Department: Casting
 Machine: TBL-23-TIE-H8
 Model Number:
 Manufacturer:
 Serial Number: TBL-23-TIE-H8

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Crane(s) and/or forklift(s) in good working order. Daily inspection log up to date.		N/A		
12	All equipment in good working order with proper guarding.		Pass		
13	Compressed gas cylinders clean, stored safely and secure.		N/A		
14	Extension cords and torch hoses do not pose a tripping hazard.		N/A		
15	There are no leaks; (oil, gas, water or compressed air).		Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 2 minutes
Auditor: Randy Rickard
Inspected Date: Mar 11, 2024

Department: Casting
Machine: TBL-23-TIE-H8
Model Number:
Manufacturer:
Serial Number: TBL-23-TIE-H8

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
16	Storage shelves and are in good condition and are loaded only to capacity.		N/A		
17	HVAC and exhaust system in working order and being used.		Pass		

Initials	General Manager	Production Manager	Supervisor		Employee
----------	-----------------	--------------------	------------	---	----------