

Inspection Report

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 2 minutes

Auditor: Dave Gaudreau

Inspected Date: Mar 11, 2024

Department: Machine Shop

Machine: Piranha Iron Worker

Model Number: P70

Manufacturer: Piranha

Serial Number: P70-1206

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Crush, amputation	2	2	1	PR2 4	Clamp in front of shear. Movable guard around punch. Guard at rear of shear and guard around punch.	Pass		
2	Third Party Protection	Crush, amputation	2	2	1	PR2 4	Same as point of operation. Painted hazard area on floor around Piranha.	Pass		
3	Power Transmission	Crush	2	2	1	PR2 4	Fixed barriers	Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 2 minutes
Auditor: Dave Gaudreau
Inspected Date: Mar 11, 2024

Department: Machine Shop
Machine: Piranha Iron Worker
Model Number: P70
Manufacturer: Piranha
Serial Number: P70-1206

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 2 minutes
 Auditor: Dave Gaudreau
 Inspected Date: Mar 11, 2024

Department: Machine Shop
 Machine: Piranha Iron Worker
 Model Number: P70
 Manufacturer: Piranha
 Serial Number: P70-1206

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?		Pass		
2	Are Emergency Exits clearly identified?		Pass		
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Pass		
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Pass		
5	Are the Eyewash Stations working and clean, and unobstructed?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 2 minutes
 Auditor: Dave Gaudreau
 Inspected Date: Mar 11, 2024

Department: Machine Shop
 Machine: Piranha Iron Worker
 Model Number: P70
 Manufacturer: Piranha
 Serial Number: P70-1206

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Is Access to the Electrical Panels clear and unobstructed?		Pass		
7	Are carts in good condition?		Pass		
8	Is the lighting all functioning properly and adequate for the area?		Pass		
9	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		
10	Is the temperature in the area comfortable to work in?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 2 minutes
 Auditor: Dave Gaudreau
 Inspected Date: Mar 11, 2024

Department: Machine Shop
 Machine: Piranha Iron Worker
 Model Number: P70
 Manufacturer: Piranha
 Serial Number: P70-1206

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
12	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass		
13	Are the employees using their PPE?		Pass		
14	Are all controlled substances labelled in accordance with GHS standards?		Pass		