

Inspection Report Summary

Department: Rod Machining

Machine: Okuma WC 121 (M121)

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 27 minutes

Auditor: Ruben Abrenica

Inspected Date: May 15, 2024

Inspection Report

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 27 minutes

Auditor: Ruben Abrenica

Inspected Date: May 15, 2024

Department: Rod Machining

Machine: Okuma WC 121 (M121)

Model Number: LB35II

Manufacturer: Okuma

Serial Number: 0279

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Load Material	crush-accidental activation	2	2	2	PR1 8	2-hand control	Pass		
2	Run Parts	Entanglement in rotating chuck or part	3	2	2	PR1 12	Interlocked Door	Pass		
3	Running Special Jobs (Long Tubes)	Entanglement in rotating chuck or part	2	1	2	PR2 4	Enclosure with Door	Pass		
4	Service Power Transmission	Crush,Entanglement-contact with power transmission	2	2	2	PR1 8	Fixed Covers	Pass		
5	Remove Waste	Pinch or drawn in by swarf conveyor.	2	2	2	PR1 8	Fixed Covers	Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 27 minutes
Auditor: Ruben Abrenica
Inspected Date: May 15, 2024

Department: Rod Machining
Machine: Okuma WC 121 (M121)
Model Number: LB35II
Manufacturer: Okuma
Serial Number: 0279

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 27 minutes
 Auditor: Ruben Abrenica
 Inspected Date: May 15, 2024

Department: Rod Machining
 Machine: Okuma WC 121 (M121)
 Model Number: LB35II
 Manufacturer: Okuma
 Serial Number: 0279

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?		Pass		
2	Are Emergency Exits clearly identified?		Pass		
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		N/A		
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		N/A		
5	Are the Eyewash Stations working and clean, and unobstructed?		N/A		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 27 minutes
 Auditor: Ruben Abrenica
 Inspected Date: May 15, 2024

Department: Rod Machining
 Machine: Okuma WC 121 (M121)
 Model Number: LB35II
 Manufacturer: Okuma
 Serial Number: 0279

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Are all the sprinkler heads in your location unobstructed?		Pass		
7	Is Access to the Electrical Panels clear and unobstructed?		N/A		
8	Are carts in good condition?		Pass		
9	Is the lighting all functioning properly and adequate for the area?		Pass		
10	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 27 minutes
 Auditor: Ruben Abrenica
 Inspected Date: May 15, 2024

Department: Rod Machining
 Machine: Okuma WC 121 (M121)
 Model Number: LB35II
 Manufacturer: Okuma
 Serial Number: 0279

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Is the temperature in the area comfortable to work in?		Pass		
12	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
13	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass		
14	Are the employees using their PPE?		Pass		
15	Are all controlled substances labelled in accordance with GHS standards?		N/A		

Initials	General Manager	Production Manager	Supervisor		Employee
----------	-----------------	--------------------	------------	---	----------