

Inspection Report Summary

Department: Green Sand Molding

Machine: 1620 Green Sand Molding #4051

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Willi Fast

Inspected Date: Sep 25, 2024

Inspection Report

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Willi Fast

Inspected Date: Sep 25, 2024

Department: Green Sand Molding

Machine: 1620 Green Sand Molding #4051

Model Number: N/A

Manufacturer: Beardsley & Piper

Serial Number: 4051

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Crush in actuating tables.	3	2	2	PR1 12	Light Curtain, Fixed Barriers	Pass		
2	Point of Operation	Crush in actuating tables.	3	2	2	PR1 12	Light Curtain	Pass		
3	Point of Operation	Crush in actuating tables.	3	2	2	PR1 12	Light Curtain, Fixed Barriers	Pass		
4	Third Party Protection	Crush in actuating tables - access from rear	3	2	2	PR1 12	Perimeter Fence	Pass		
5	Power Transmission	Crush in actuating parts.	3	2	2	PR1 12	Fixed guarding	Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Willi Fast
Inspected Date: Sep 25, 2024

Department: Green Sand Molding
Machine: 1620 Green Sand Molding #4051
Model Number: N/A
Manufacturer: Beardsley & Piper
Serial Number: 4051

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 0 minutes
 Auditor: Willi Fast
 Inspected Date: Sep 25, 2024

Department: Green Sand Molding
 Machine: 1620 Green Sand Molding #4051
 Model Number: N/A
 Manufacturer: Beardsley & Piper
 Serial Number: 4051

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?		Pass		
2	Are Emergency Exits clearly identified?		Pass		
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Pass		
5	Are the Eyewash Stations working and clean, and unobstructed?		Pass		
6	Are all the sprinkler heads in your location unobstructed?		N/A		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 0 minutes
 Auditor: Willi Fast
 Inspected Date: Sep 25, 2024

Department: Green Sand Molding
 Machine: 1620 Green Sand Molding #4051
 Model Number: N/A
 Manufacturer: Beardsley & Piper
 Serial Number: 4051

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
7	Is Access to the Electrical Panels clear and unobstructed?		Pass		
8	Are carts in good condition?		Pass		
9	Is the lighting all functioning properly and adequate for the area?		Pass		
10	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		
11	Is the temperature in the area comfortable to work in?		Pass		

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 0 minutes
 Auditor: Willi Fast
 Inspected Date: Sep 25, 2024

Department: Green Sand Molding
 Machine: 1620 Green Sand Molding #4051
 Model Number: N/A
 Manufacturer: Beardsley & Piper
 Serial Number: 4051

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
12	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
13	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass		
14	Are the employees using their PPE?		Pass		
15	Are all controlled substances labelled in accordance with GHS standards?		Pass		