

Inspection Report Summary

Department: Welding

Machine: Miller WC 552 (M12)

Pass / Fail: 95% Passed / 5% Failed

Time to Conduct Audit: 6 minutes

Auditor: Jon Kilcullen

Inspected Date: Oct 10, 2024

Inspection Report

Pass / Fail: 95% Passed / 5% Failed

Time to Conduct Audit: 6 minutes

Auditor: Jon Kilcullen

Inspected Date: Oct 10, 2024

Department: Welding

Machine: Miller WC 552 (M12)

Model Number: N/A

Manufacturer: Miller

Serial Number: N/A

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Entanglement or crush in rotating parts. Welding burn or flash from rod.	2	2	1	PR2 4	Interlocked chuck door. Welding curtain.	Pass		
2	Third Party Protection	Entanglement or crush in rotating parts. Welding burn or flash from rod.	2	2	1	PR2 4	Welding curtains	Pass		
3	Power Transmission	Entanglement or crush	2	2	1	PR2 4	barrier guards	Pass		
4	Other Hazards	Fumes	2	2	1	PR2 4	Extraction	Pass		

Pass / Fail: 95% Passed / 5% Failed
Time to Conduct Audit: 6 minutes
Auditor: Jon Kilcullen
Inspected Date: Oct 10, 2024

Department: Welding
Machine: Miller WC 552 (M12)
Model Number: N/A
Manufacturer: Miller
Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?	Get it posted	Fail		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 95% Passed / 5% Failed
 Time to Conduct Audit: 6 minutes
 Auditor: Jon Kilcullen
 Inspected Date: Oct 10, 2024

Department: Welding
 Machine: Miller WC 552 (M12)
 Model Number: N/A
 Manufacturer: Miller
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?		N/A		
2	Are Emergency Exits clearly identified?		N/A		
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Pass		
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Pass		
5	Are the Eyewash Stations working and clean, and unobstructed?		Pass		

Pass / Fail: 95% Passed / 5% Failed
 Time to Conduct Audit: 6 minutes
 Auditor: Jon Kilcullen
 Inspected Date: Oct 10, 2024

Department: Welding
 Machine: Miller WC 552 (M12)
 Model Number: N/A
 Manufacturer: Miller
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Are all the sprinkler heads in your location unobstructed?		Pass		
7	Is Access to the Electrical Panels clear and unobstructed?		Pass		
8	Are carts in good condition?		Pass		
9	Is the lighting all functioning properly and adequate for the area?		Pass		
10	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		

Pass / Fail: 95% Passed / 5% Failed
 Time to Conduct Audit: 6 minutes
 Auditor: Jon Kilcullen
 Inspected Date: Oct 10, 2024

Department: Welding
 Machine: Miller WC 552 (M12)
 Model Number: N/A
 Manufacturer: Miller
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Is the temperature in the area comfortable to work in?		Pass		
12	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
13	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass		
14	Are the employees using their PPE?		Pass		
15	Are all controlled substances labelled in accordance with GHS standards?		Pass		

Initials	General Manager	Production Manager	Supervisor 	Employee 
----------	-----------------	--------------------	--	--