

Inspection Report Summary

Department: Assembly

Machine: Station 4 WC 628 (Welded Assembly)

Auditor: Loreto Jimenez

Inspected Date: Dec 18, 2024

Inspection Report

Auditor: Loreto Jimenez
Inspected Date: Dec 18, 2024

Department: Assembly
Machine: Station 4 WC 628 (Welded Assembly)
Model Number:
Manufacturer:
Serial Number:

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Test Parts	Struck by - fitting	2	2	2	PR1 8	Low Air Pressure			

Auditor: Loreto Jimenez
Inspected Date: Dec 18, 2024

Department: Assembly
Machine: Station 4 WC 628 (Welded Assembly)
Model Number:
Manufacturer:
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
--	----------	-------------------	-----------	-------------------	-------------

Auditor: Loreto Jimenez
Inspected Date: Dec 18, 2024

Department: Assembly
Machine: Station 4 WC 628 (Welded Assembly)
Model Number:
Manufacturer:
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
--	----------	-------------------	-----------	-------------------	-------------