

Inspection Report Summary

Department: Melting

Machine: Pouring Line - Machine #4453

Pass / Fail: 94% Passed / 6% Failed

Time to Conduct Audit: 9 minutes

Auditor: Dave Rempel

Inspected Date: Jan 15, 2025

Inspection Report

Pass / Fail: 94% Passed / 6% Failed

Time to Conduct Audit: 9 minutes

Auditor: Dave Rempel

Inspected Date: Jan 15, 2025

Department: Melting

Machine: Pouring Line - Machine #4453

Model Number: N/A

Manufacturer: N/A

Serial Number: N/A

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Pour Material	Crush, Burn, Struck By	2	2	2	PR1 8	Admin, PPE	Pass		
2	Access Deck (Third Parties)	Burn, Crush, Struck By	2	2	2	PR1 8	Spring loaded awareness gates and signage have been installed	Pass		
3	Walk on Deck	entanglement	2	2	2	PR1 8	fixed covers	Pass		

Pass / Fail: 94% Passed / 6% Failed
Time to Conduct Audit: 9 minutes
Auditor: Dave Rempel
Inspected Date: Jan 15, 2025

Department: Melting
Machine: Pouring Line - Machine #4453
Model Number: N/A
Manufacturer: N/A
Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 94% Passed / 6% Failed
 Time to Conduct Audit: 9 minutes
 Auditor: Dave Rempel
 Inspected Date: Jan 15, 2025

Department: Melting
 Machine: Pouring Line - Machine #4453
 Model Number: N/A
 Manufacturer: N/A
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?		Pass		
2	Are Emergency Exits clearly identified?		Pass		
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?	Hook missing on bottle	Fail		
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Pass		
5	Are the Eyewash Stations working and clean, and unobstructed?		N/A		

Pass / Fail: 94% Passed / 6% Failed
 Time to Conduct Audit: 9 minutes
 Auditor: Dave Rempel
 Inspected Date: Jan 15, 2025

Department: Melting
 Machine: Pouring Line - Machine #4453
 Model Number: N/A
 Manufacturer: N/A
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Are all the sprinkler heads in your location unobstructed?		N/A		
8	Are carts in good condition?		Pass		
9	Is the lighting all functioning properly and adequate for the area?		Pass		
10	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		
11	Is the temperature in the area comfortable to work in?		Pass		

Pass / Fail: 94% Passed / 6% Failed
 Time to Conduct Audit: 9 minutes
 Auditor: Dave Rempel
 Inspected Date: Jan 15, 2025

Department: Melting
 Machine: Pouring Line - Machine #4453
 Model Number: N/A
 Manufacturer: N/A
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
12	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
13	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass		
14	Are the employees using their PPE?		Pass		
15	Are all controlled substances labelled in accordance with GHS standards?		Pass		