

Inspection Report Summary

Department: Cold Storage - Out of Service

Machine: GRIND-02-BALDOR

Time to Conduct Audit: 19 minutes

Auditor: Matt Dodd

Inspected Date: Feb 11, 2025

Inspection Report

Time to Conduct Audit: 19 minutes

Auditor: Matt Dodd

Inspected Date: Feb 11, 2025

Department: Cold Storage - Out of Service

Machine: GRIND-02-BALDOR

Model Number:

Manufacturer: Baldor

Serial Number: 530

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Grind part	Struck by debris	2	1	2	PR2 4	none			
2	Grind part	Entangle in power transmission	2	1	2	PR2 4	Partial guard around discs			
3	Grind part	Struck by part	2	1	2	PR2 4	none			

Time to Conduct Audit: 19 minutes
Auditor: Matt Dodd
Inspected Date: Feb 11, 2025

Department: Cold Storage - Out of Service
Machine: GRIND-02-BALDOR
Model Number:
Manufacturer: Baldor
Serial Number: 530

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?				
2	Are all Emergency Stops clearly marked and functioning properly?				

Time to Conduct Audit: 19 minutes
Auditor: Matt Dodd
Inspected Date: Feb 11, 2025

Department: Cold Storage - Out of Service
Machine: GRIND-02-BALDOR
Model Number:
Manufacturer: Baldor
Serial Number: 530

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	The floors are clear of debris, loose material and trip hazards.				
2	The floors are not slippery or wet and there are no spills.				
3	Floors around furnaces and equipment are in good condition.				
4	Aisle are clear, no obstructions.				
5	Exits are clear and functioning.				

Time to Conduct Audit: 19 minutes
Auditor: Matt Dodd
Inspected Date: Feb 11, 2025

Department: Cold Storage - Out of Service
Machine: GRIND-02-BALDOR
Model Number:
Manufacturer: Baldor
Serial Number: 530

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Fire extinguishers are clear of obstruction and are inspected regularly.				
7	Fire blanket(s) are in their holders and instructions are legible.				
8	Electrical panels have one meter clearance and are free of clutter.				
9	Chemical substances are properly labelled.				
10	Required Personal Protective Equipment (PPE) is available and being worn.				

Time to Conduct Audit: 19 minutes
Auditor: Matt Dodd
Inspected Date: Feb 11, 2025

Department: Cold Storage - Out of Service
Machine: GRIND-02-BALDOR
Model Number:
Manufacturer: Baldor
Serial Number: 530

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Crane(s) and/or forklift(s) in good working order. Daily inspection log up to date.				
12	All equipment in good working order with proper guarding.				
13	Compressed gas cylinders clean, stored safely and secure.				
14	Extension cords and torch hoses do not pose a tripping hazard.				
15	There are no leaks; (oil, gas, water or compressed air).				

Time to Conduct Audit: 19 minutes
Auditor: Matt Dodd
Inspected Date: Feb 11, 2025

Department: Cold Storage - Out of Service
Machine: GRIND-02-BALDOR
Model Number:
Manufacturer: Baldor
Serial Number: 530

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
16	Storage shelves and are in good condition and are loaded only to capacity.				
17	HVAC and exhaust system in working order and being used.				