

Inspection Report Summary

Department: QA

Machine: QA Bench Grinder

Time to Conduct Audit: 0 minutes

Auditor: Sivakumar Seru

Inspected Date: Feb 14, 2025

Inspection Report

Time to Conduct Audit: 0 minutes
Auditor: Sivakumar Seru
Inspected Date: Feb 14, 2025

Department: QA
Machine: QA Bench Grinder
Model Number: 55-3516-6
Manufacturer: Mastercraft
Serial Number: 50118

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Grind Parts	Entanglement in disc. Abrasion.	2	1	2	PR2 4	Awareness Shields			

Time to Conduct Audit: 0 minutes
Auditor: Sivakumar Seru
Inspected Date: Feb 14, 2025

Department: QA
Machine: QA Bench Grinder
Model Number: 55-3516-6
Manufacturer: Mastercraft
Serial Number: 50118

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?				
2	Are all Emergency Stops clearly marked and functioning properly?				

Time to Conduct Audit: 0 minutes
Auditor: Sivakumar Seru
Inspected Date: Feb 14, 2025

Department: QA
Machine: QA Bench Grinder
Model Number: 55-3516-6
Manufacturer: Mastercraft
Serial Number: 50118

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?				
2	Are Emergency Exits clearly identified?				
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?				
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?				
5	Are the Eyewash Stations working and clean, and unobstructed?				

Time to Conduct Audit: 0 minutes
Auditor: Sivakumar Seru
Inspected Date: Feb 14, 2025

Department: QA
Machine: QA Bench Grinder
Model Number: 55-3516-6
Manufacturer: Mastercraft
Serial Number: 50118

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Are all the sprinkler heads in your location unobstructed?				
7	Is Access to the Electrical Panels clear and unobstructed?				
8	Are carts in good condition?				
9	Is the lighting all functioning properly and adequate for the area?				
10	Are noise levels adequate with PPE, any high impulse or continual noise?				

Time to Conduct Audit: 0 minutes
Auditor: Sivakumar Seru
Inspected Date: Feb 14, 2025

Department: QA
Machine: QA Bench Grinder
Model Number: 55-3516-6
Manufacturer: Mastercraft
Serial Number: 50118

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Is the temperature in the area comfortable to work in?				
12	Are all air quality systems working (dust, fumes or vapour present)?				
13	Is the housekeeping (floor and work surfaces) sufficient for the area?				
14	Are the employees using their PPE?				
15	Are all controlled substances labelled in accordance with GHS standards?				