

Inspection Report Summary

Department: Machine Shop

Machine: Rotary 4 Post Bluetooth Hoist

Auditor: Dave Gaudreau

Inspected Date: Mar 18, 2025

Inspection Report

Auditor: Dave Gaudreau
Inspected Date: Mar 18, 2025

Department: Machine Shop
Machine: Rotary 4 Post Bluetooth Hoist
Model Number: MCHW418U101
Manufacturer: Rotary
Serial Number: HBE16B0040

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Crush	3	2	2	PR1 12	Hold to run controls located on far side of post			
2	Third Party Protection	Crush	3	2	2	PR1 12	Use a safety watcher to ensure area is clear			
3	Power Transmission	Crush	3	2	2	PR1 12	Fixed guard			

Auditor: Dave Gaudreau
Inspected Date: Mar 18, 2025

Department: Machine Shop
Machine: Rotary 4 Post Bluetooth Hoist
Model Number: MCHW418U101
Manufacturer: Rotary
Serial Number: HBE16B0040

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
--	----------	-------------------	-----------	-------------------	-------------

Auditor: Dave Gaudreau
Inspected Date: Mar 18, 2025

Department: Machine Shop
Machine: Rotary 4 Post Bluetooth Hoist
Model Number: MCHW418U101
Manufacturer: Rotary
Serial Number: HBE16B0040

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
--	----------	-------------------	-----------	-------------------	-------------