

Inspection Report Summary

Department: Shipping

Machine: Outfeed Conveyors

Pass / Fail: 82% Passed / 18% Failed

Time to Conduct Audit: 266 minutes

Auditor: Lidong Wang

Inspected Date: Apr 10, 2025

Inspection Report

Pass / Fail: 82% Passed / 18% Failed

Time to Conduct Audit: 266 minutes

Auditor: Lidong Wang

Inspected Date: Apr 10, 2025

Department: Shipping

Machine: Outfeed Conveyors

Model Number: N/A

Manufacturer: N/A

Serial Number: N/A

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Storage Bays - Crush hazard, falling object crush hazard, hit hazard from falling objects, fall hazards from climbing on product, strain hazards from trying to push or move product by hand	3	2	2	PR1 12	Standard Operating Procedure to stack units in best method possible to maintain stack integrity, minimize pedestrian traffic in this zone, personnel not to climb on product because of load instability, and get help or use forklift if aid is required to move load	Pass		

Pass / Fail: 82% Passed / 18% Failed
 Time to Conduct Audit: 266 minutes
 Auditor: Lidong Wang
 Inspected Date: Apr 10, 2025

Department: Shipping
 Machine: Outfeed Conveyors
 Model Number: N/A
 Manufacturer: N/A
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 82% Passed / 18% Failed
 Time to Conduct Audit: 266 minutes
 Auditor: Lidong Wang
 Inspected Date: Apr 10, 2025

Department: Shipping
 Machine: Outfeed Conveyors
 Model Number: N/A
 Manufacturer: N/A
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?	Walkway blocked	Fail		
2	Are Emergency Exits clearly identified?		Pass		
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Pass		
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Pass		
5	Are the Eyewash Stations working and clean, and unobstructed?	Pallet to be organized, bike shouldn't be in building	Fail		

Pass / Fail: 82% Passed / 18% Failed
 Time to Conduct Audit: 266 minutes
 Auditor: Lidong Wang
 Inspected Date: Apr 10, 2025

Department: Shipping
 Machine: Outfeed Conveyors
 Model Number: N/A
 Manufacturer: N/A
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Are all the sprinkler heads in your location unobstructed?		Pass		
7	Is Access to the Electrical Panels clear and unobstructed?		Pass		
9	Is the lighting all functioning properly and adequate for the area?		Pass		
10	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		
11	Is the temperature in the area comfortable to work in?		Pass		

Pass / Fail: 82% Passed / 18% Failed
 Time to Conduct Audit: 266 minutes
 Auditor: Lidong Wang
 Inspected Date: Apr 10, 2025

Department: Shipping
 Machine: Outfeed Conveyors
 Model Number: N/A
 Manufacturer: N/A
 Serial Number: N/A

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
12	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
13	Is the housekeeping (floor and work surfaces) sufficient for the area?	Floor sweep	Fail		
14	Are the employees using their PPE?		Pass		
15	Are all controlled substances labelled in accordance with GHS standards?		Pass		