

Inspection Report Summary

Department: Metal Shop

Machine: Grinder

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 1 minutes

Auditor: EHS Consulting

Inspected Date: Apr 24, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 1 minutes

Auditor: EHS Consulting

Inspected Date: Apr 24, 2025

Department: Metal Shop

Machine: Grinder

Model Number:

Manufacturer: Delta

Serial Number: PTSD15-000343

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Grind Parts	Abrasion, Entanglement -contact with wheel	2	2	2	PR1 8	Awareness Shield	Pass		
2	Grind Parts	Struck by - part comes free	2	2	2	PR1 8	Tool Rest	Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 1 minutes
Auditor: EHS Consulting
Inspected Date: Apr 24, 2025

Department: Metal Shop
Machine: Grinder
Model Number:
Manufacturer: Delta
Serial Number: PTSD15-000343

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?				
2	Are all Emergency Stops clearly marked and functioning properly?				

Initials	General Manager	Production Manager	Supervisor	Employee	
----------	-----------------	--------------------	------------	----------	---