

Inspection Report Summary

Department: Metal Shop

Machine: PAL Air Compressor

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Kristin Petaski

Inspected Date: Apr 24, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Kristin Petaski

Inspected Date: Apr 24, 2025

Department: Metal Shop

Machine: PAL Air Compressor

Model Number: 5HP 60 Gal

Manufacturer: PAL Manufacturing

Serial Number: 130-67859

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Run compressor	Entangle, crush in power transmission	2	2	2	PR18	Fixed guard	Pass		
2	Run compressor	Explosion - over pressure	3	2	2	PR112	Rated with relief valve	Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Kristin Petaski
Inspected Date: Apr 24, 2025

Department: Metal Shop
Machine: PAL Air Compressor
Model Number: 5HP 60 Gal
Manufacturer: PAL Manufacturing
Serial Number: 130-67859

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?				
2	Are all Emergency Stops clearly marked and functioning properly?				