

# Inspection Report Summary

Department: Metalworking

Machine: Bio-Circle Parts Washer

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Jacob Tsai

Inspected Date: May 14, 2025

# Inspection Report

Pass / Fail: 100% Passed / 0% Failed  
Time to Conduct Audit: 0 minutes  
Auditor: Jacob Tsai  
Inspected Date: May 14, 2025

Department: Metalworking  
Machine: Bio-Circle Parts Washer  
Model Number:  
Manufacturer: Bio-Circle  
Serial Number:

|   | Activity Task | Hazard                             | Sev | Exp | Avd | Total    | Current Safeguards | Corrective Action | WO Num | Assigned to |
|---|---------------|------------------------------------|-----|-----|-----|----------|--------------------|-------------------|--------|-------------|
| 1 | Wash parts    | Struck by water, chemical solution | 1   | 2   | 2   | PR3<br>4 | Basin, PPE         |                   |        |             |

Pass / Fail: 100% Passed / 0% Failed  
Time to Conduct Audit: 0 minutes  
Auditor: Jacob Tsai  
Inspected Date: May 14, 2025

Department: Metalworking  
Machine: Bio-Circle Parts Washer  
Model Number:  
Manufacturer: Bio-Circle  
Serial Number:

|   | Question                                                         | Corrective Action | Pass/Fail | Work Order Number | Assigned to |
|---|------------------------------------------------------------------|-------------------|-----------|-------------------|-------------|
| 1 | Safe Work Procedure posted?                                      |                   | Pass      |                   |             |
| 2 | Are all Emergency Stops clearly marked and functioning properly? |                   | Pass      |                   |             |