

Inspection Report Summary

Department: Metalworking

Machine: Beverley Shear

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Jacob Tsai

Inspected Date: May 14, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Jacob Tsai
Inspected Date: May 14, 2025

Department: Metalworking
Machine: Beverley Shear
Model Number: B3
Manufacturer: Beverley
Serial Number: PTSD-000277

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Cut part	Laceration, amputation from blade	2	2	1	PR2 4	Manual operation, hazard markings			

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Jacob Tsai
Inspected Date: May 14, 2025

Department: Metalworking
Machine: Beverley Shear
Model Number: B3
Manufacturer: Beverley
Serial Number: PTSD-000277

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Initials	General Manager	Production Manager	Supervisor	Employee	Jacob Tsai
----------	-----------------	--------------------	------------	----------	------------