

Inspection Report Summary

Department: Graphic Arts

Machine: Vastex Silk Screen Table

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Jacob Tsai

Inspected Date: May 14, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Jacob Tsai

Inspected Date: May 14, 2025

Department: Graphic Arts

Machine: Vastex Silk Screen Table

Model Number: V-2000HD

Manufacturer: Vastex

Serial Number:

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Stretch material	Pinch in clamps	1	1	1	PR4 1	Manual clamps			
2	Operate table	Pinch in springs	1	2	2	PR3 4	Manual operation, fixed guards			

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Jacob Tsai
Inspected Date: May 14, 2025

Department: Graphic Arts
Machine: Vastex Silk Screen Table
Model Number: V-2000HD
Manufacturer: Vastex
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		