

Inspection Report Summary

Department: Woodworking

Machine: Rikon Band Saw

Time to Conduct Audit: 0 minutes

Auditor: Kristin Petaski

Inspected Date: May 14, 2025

Inspection Report

Time to Conduct Audit: 0 minutes

Auditor: Kristin Petaski

Inspected Date: May 14, 2025

Department: Woodworking

Machine: Rikon Band Saw

Model Number: 10-326 (1.75 hp, 115/230V, 14/7A)

Manufacturer: Rikon

Serial Number: 21072122071

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Cut part	Amputation from blade	2	2	2	PR1 8	Adjustable blade guard			
2	Third party access	Laceration, amputation from blade	2	2	2	PR1 8	Blade guard, located against wall, hazard markings on floor			
3	Change blade	Crush in power transmission	2	1	2	PR2 4	Secured power transmission guard			

Time to Conduct Audit: 0 minutes
Auditor: Kristin Petaski
Inspected Date: May 14, 2025

Department: Woodworking
Machine: Rikon Band Saw
Model Number: 10-326 (1.75 hp, 115/230V, 14/7A)
Manufacturer: Rikon
Serial Number: 21072122071

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
--	----------	-------------------	-----------	-------------------	-------------

Initials	General Manager	Production Manager	Supervisor	Employee	KCP
----------	-----------------	--------------------	------------	----------	-----