

Inspection Report Summary

Department: STEM Lab

Machine: Ultimaker 2+ 3D Printer #1

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 1 minutes

Auditor: Jacob Tsai

Inspected Date: May 14, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 1 minutes
Auditor: Jacob Tsai
Inspected Date: May 14, 2025

Department: STEM Lab
Machine: Ultimaker 2+ 3D Printer #1
Model Number: 2+
Manufacturer: Ultimaker
Serial Number: #1

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Print part	Struck by carriage, burn from extruder	1	2	2	PR3 4	Enclosure with hinged door.			

Pass / Fail: 100% Passed / 0% Failed
 Time to Conduct Audit: 1 minutes
 Auditor: Jacob Tsai
 Inspected Date: May 14, 2025

Department: STEM Lab
 Machine: Ultimaker 2+ 3D Printer #1
 Model Number: 2+
 Manufacturer: Ultimaker
 Serial Number: #1

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		