

Inspection Report Summary

Department: STEM Lab

Machine: Ultimaker 2+ 3D Printer #3

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Jacob Tsai

Inspected Date: May 14, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Jacob Tsai
Inspected Date: May 14, 2025

Department: STEM Lab
Machine: Ultimaker 2+ 3D Printer #3
Model Number: 2+
Manufacturer: Ultimaker
Serial Number: #3

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Print part	Struck by carriage, burn from extruder	1	2	2	PR3 4	Enclosure with hinged door.			

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Jacob Tsai
Inspected Date: May 14, 2025

Department: STEM Lab
Machine: Ultimaker 2+ 3D Printer #3
Model Number: 2+
Manufacturer: Ultimaker
Serial Number: #3

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Initials	General Manager	Production Manager	Supervisor	Employee	Jacob Tsai
----------	-----------------	--------------------	------------	----------	------------