

Inspection Report Summary

Department: Wood Shop

Machine: Laguna Wood Lathe

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Kristin Petaski

Inspected Date: May 15, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Kristin Petaski

Inspected Date: May 15, 2025

Department: Wood Shop

Machine: Laguna Wood Lathe

Model Number: Revo 23/36 (230v, 3hp, 1ph)

Manufacturer: Laguna

Serial Number: 22020912

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Shape part	Entangle, struck by debris	3	2	2	PR1 12	Awareness shield over front of machine	Pass		
2	Operate machine	Crush in power transmission	2	2	2	PR1 8	Secure pulley access door	Pass		
3	Third-party access	Entangle, struck by debris	3	2	2	PR1 12	Rear guard	Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Kristin Petaski
Inspected Date: May 15, 2025

Department: Wood Shop
Machine: Laguna Wood Lathe
Model Number: Revo 23/36 (230v, 3hp, 1ph)
Manufacturer: Laguna
Serial Number: 22020912

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?				
2	Are all Emergency Stops clearly marked and functioning properly?				