

Inspection Report Summary

Department: STEM Lab

Machine: Ultimaker 2+ 3D Printer

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Kristin Petaski

Inspected Date: May 15, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Kristin Petaski
Inspected Date: May 15, 2025

Department: STEM Lab
Machine: Ultimaker 2+ 3D Printer
Model Number: 2+
Manufacturer: Ultimaker
Serial Number:

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Print part	Crush, burn	1	2	1	PR3 2	Fixed enclosure guard	Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Kristin Petaski
Inspected Date: May 15, 2025

Department: STEM Lab
Machine: Ultimaker 2+ 3D Printer
Model Number: 2+
Manufacturer: Ultimaker
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?				
2	Are all Emergency Stops clearly marked and functioning properly?				