

Inspection Report Summary

Department: Graphics Lab

Machine: Epilog Laser Engraver

Pass / Fail: 100% Passed / 0% Failed

Time to Conduct Audit: 0 minutes

Auditor: Jacob Tsai

Inspected Date: May 15, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Jacob Tsai
Inspected Date: May 15, 2025

Department: Graphics Lab
Machine: Epilog Laser Engraver
Model Number: FusionPro
Manufacturer: Epilog
Serial Number: 17000-23064153624

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Operate machine	Burn from laser, crush in power transmission	3	2	2	PR1 12	Interlocked enclosure guard			

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 0 minutes
Auditor: Jacob Tsai
Inspected Date: May 15, 2025

Department: Graphics Lab
Machine: Epilog Laser Engraver
Model Number: FusionPro
Manufacturer: Epilog
Serial Number: 17000-23064153624

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Initials	General Manager	Production Manager	Supervisor	Employee
				