

Inspection Report Summary

Department: Machine Shop

Machine: Piranha Iron Worker

Auditor: Dave Gaudreau

Inspected Date: May 20, 2025

Inspection Report

Auditor: Dave Gaudreau
Inspected Date: May 20, 2025

Department: Machine Shop
Machine: Piranha Iron Worker
Model Number: P70
Manufacturer: Piranha
Serial Number: P70-1206

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Point of Operation	Crush, amputation	2	2	1	PR2 4	Clamp in front of shear. Movable guard around punch. Guard at rear of shear and guard around punch.			
2	Third Party Protection	Crush, amputation	2	2	1	PR2 4	Same as point of operation. Painted hazard area on floor around Piranha.			
3	Power Transmission	Crush	2	2	1	PR2 4	Fixed barriers			

Auditor: Dave Gaudreau
Inspected Date: May 20, 2025

Department: Machine Shop
Machine: Piranha Iron Worker
Model Number: P70
Manufacturer: Piranha
Serial Number: P70-1206

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
--	----------	-------------------	-----------	-------------------	-------------

Auditor: Dave Gaudreau
Inspected Date: May 20, 2025

Department: Machine Shop
Machine: Piranha Iron Worker
Model Number: P70
Manufacturer: Piranha
Serial Number: P70-1206

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
--	----------	-------------------	-----------	-------------------	-------------