Inspection Report Summary

Department: Paint Line
Machine: Manual Booth - Topcoat WC631

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 10 minutes
Auditor: Romel Marquez
Inspected Date: May 30, 2025

Inspection Report

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 10 minutes
Auditor: Romel Marquez
Inspected Date: May 30, 2025

Department: Paint Line
Machine: Manual Booth - Topcoat WC631
Model Number:
Manufacturer:
Serial Number:

	Activity Task	Hazard	Sev	Exp	Avd	Total	Current Safeguards	Corrective Action	WO Num	Assigned to
1	Paint Parts	Fumes	2	2	2	PR1 8	Interlocked Door, PPE	**Pass**		
2	Fill Paint	Explosion, Fire	2	2	2	PR1 8	Grounding	**Pass**		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 10 minutes
Auditor: Romel Marquez
Inspected Date: May 30, 2025

Department: Paint Line
Machine: Manual Booth - Topcoat WC631
Model Number:
Manufacturer:
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Safe Work Procedure posted?		Pass		
2	Are all Emergency Stops clearly marked and functioning properly?		Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 10 minutes
Auditor: Romel Marquez
Inspected Date: May 30, 2025

Department: Paint Line
Machine: Manual Booth - Topcoat WC631
Model Number:
Manufacturer:
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
1	Are Emergency Exits clear and unobstructed?		Pass		
2	Are Emergency Exits clearly identified?		Pass		
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Pass		
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Pass		
5	Are the Eyewash Stations working and clean, and unobstructed?		Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 10 minutes
Auditor: Romel Marquez
Inspected Date: May 30, 2025

Department: Paint Line
Machine: Manual Booth - Topcoat WC631
Model Number:
Manufacturer:
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
6	Are all the sprinkler heads in your location unobstructed?		Pass		
7	Is Access to the Electrical Panels clear and unobstructed?		Pass		
8	Are carts in good condition?		N\A		
9	Is the lighting all functioning properly and adequate for the area?		Pass		
10	Are noise levels adequate with PPE, any high impulse or continual noise?		Pass		

Pass / Fail: 100% Passed / 0% Failed
Time to Conduct Audit: 10 minutes
Auditor: Romel Marquez
Inspected Date: May 30, 2025

Department: Paint Line
Machine: Manual Booth - Topcoat WC631
Model Number:
Manufacturer:
Serial Number:

	Question	Corrective Action	Pass/Fail	Work Order Number	Assigned to
11	Is the temperature in the area comfortable to work in?		Pass		
12	Are all air quality systems working (dust, fumes or vapour present)?		Pass		
13	Is the housekeeping (floor and work surfaces) sufficient for the area?		Pass		
14	Are the employees using their PPE?		Pass		
15	Are all controlled substances labelled in accordance with GHS standards?		Pass		

Initials	General Manager	Production Manager	Supervisor	Employee