Inspection Report Summary

Department:	Assembly
Machine:	WC 610 Long Tube Washer M150
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	2 minutes
Auditor:	—
Inspected Date:	Aug 27, 2025

Inspection Report

Facility: Burmac

Department: Assembly

Machine: WC 610 Long Tube Washer M150

Model Number: TEW-84X24X12-E-500-55

Manufacturer: RGHanson

Serial Number: 2022-103

Machine Specific

#	Question	Corrective Action	Result
1	Safe Work Procedure posted?		**Pass**
2	Are all Emergency Stops clearly marked and functioning properly?		**Pass**

Department Specific

#	Question	Corrective Action	Result
1	Are Emergency Exits clear and unobstructed?		**Pass**
2	Are Emergency Exits clearly identified?		**Pass**
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		**Pass**
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		**Pass**
5	Are the Eyewash Stations working and clean, and unobstructed?		**Pass**
6	Are all the sprinkler heads in your location unobstructed?		**Pass**
7	Is Access to the Electrical Panels clear and unobstructed?		**Pass**
8	Are carts in good condition?		**Pass**
9	Is the lighting all functioning properly and adequate for the area?		**Pass**
10	Are noise levels adequate with PPE, any high impulse or continual noise?		**Pass**
11	Is the temperature in the area comfortable to work in?		**Pass**
12	Are all air quality systems working (dust, fumes or vapour present)?		**Pass**
13	Is the housekeeping (floor and work surfaces) sufficient for the area?		**Pass**
14	Are the employees using their PPE?		**Pass**
15	Are all controlled substances labelled in accordance with GHS standards?		**Pass**

Supervisor Signature: