

Inspection Report Summary

Department:	Melting
Machine:	Furnace #1131
Pass / Fail:	88 % Passed / 13 % Failed
Time to Audit:	171 minutes
Auditor:	—
Inspected Date:	Aug 28, 2025

Inspection Report

Facility: Winkler

Department: Melting

Machine: Furnace #1131

Model Number: N/A

Manufacturer: N/A

Serial Number: West #2




Machine Specific

#	Question	Corrective Action	Result
1	Safe Work Procedure posted?		Pass
2	Are all Emergency Stops clearly marked and functioning properly?	Place label by e-stop Assigned: Dave Rempel 	Fail

Department Specific

#	Question	Corrective Action	Result
1	Are Emergency Exits clear and unobstructed?		Pass
2	Are Emergency Exits clearly identified?		Pass
3	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Pass
4	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Pass
5	Is Access to the Electrical Panels clear and unobstructed?		Pass
6	Are all controlled substances labelled in accordance with GHS standards?		Pass

Safety Rep Signature:



Supervisor Signature:

