

Inspection Report Summary

Department:	Test
Machine:	Test Nov 21
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	12 minutes
Auditor:	Julius Tester
Inspected Date:	Nov 24, 2025

Inspection Report

Facility: EHS Demo

Department: Test

Machine: Test Nov 21

Model Number: CC

Manufacturer: BB

Serial Number: DD




#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A handwritten signature in black ink, enclosed in a rectangular box. The signature is stylized, starting with a large 'A' and ending with a loop.

Supervisor Signature:

A handwritten signature in black ink, enclosed in a rectangular box. The signature is stylized, starting with a large 'A' and ending with a loop.